



Statement

Concerning the McNetiq Controllock (model SAV 551.01-1400), the following activities have been done and completed in a satisfactory manner:

- Review of User Manual and safety document, including safe working procedures
- Team based analysis by specialists representing various disciplines (both internal and external) of the following aspects of the Controllock:
 - o Product review in view of potential hazards
 - o Human interaction with the product
 - o External influences that could influence safety of the product

The results of the team safety review have been recorded in report no. RET 0267962

In the absence of specific technical standards for this type of product a type approval procedure is not possible. Based on the information provided to us we are of the opinion the product fulfils safety requirements

C.Pluym

A handwritten signature in blue ink, appearing to read 'C. Pluym'.

Statutory Support Engineer
Rotterdam
12-12-2014